

Inspection Photos
Location Name: M & M B-65N64W/2SWSE
Location #: 306198



Photo #1
M & M B 2-23 (123-24186) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 40 yds.



Photo #2
Meyer B 2-16, M & M B 2-23 Battery site
Abandoned: ALL Equipment Removed
Plugged & Abandoned | PA
2: wells

