

Inspection Photos

Location Name: COUGAR B/02-68-1HN

Location ID: 326875



Colorado Energy & Carbon Management Commission
Weld County
+40.435748 -104.521590
232° SW
2024-05-10 14:01

Photo #1

Cougar B 02-68-1HN, B 02-69-1HN, B 02-67-1HN
Wellsite(s)

2: Producing | PR; 1: Shut-In | SI
Battery / Wellsite(s) entrance



Colorado Energy & Carbon Management Commission
Weld County
+40.434155 -104.524178
298° NW
2024-05-10 13:03

Photo #2

Cougar B 02-68-1HN, B 02-69-1HN, B 02-67-1HN
Wellsite(s)

2: Producing | PR; 1: Shut-In | SI
E → W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: COUGAR B/02-68-1HN
Location ID: 326875



Photo #3
Cougar B 02-67-1HN (123-36406) Wellsite
Producing | PR



Cougar B 02-68-1HN, B 02-69-1HN, B 02-67-1HN
Battery site
Active
Equipment Documented; Loc ID: 326875
Formerly served:
Baker B2-5, Fritzler B 02-19; Plugged & Abandoned | PA

