

## Inspection Photos

Location Name: COUGAR B/02-68-1HN

Location ID: 326875



**Photo #1**

**Cougar B 02-68-1HN, B 02-69-1HN, B 02-67-1HN**  
Wellsite(s)

**2: Producing | PR; 1: Shut-In | SI**  
*Battery / Wellsite(s) entrance*



**Photo #2**

**Cougar B 02-68-1HN, B 02-69-1HN, B 02-67-1HN**  
Wellsite(s)

**2: Producing | PR; 1: Shut-In | SI**  
*E → W*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: COUGAR B/02-68-1HN

Location ID: 326875



**Photo #3**

**Cougar B 02-69-1HN (123-36405) Wellsite**

**Shut-In | SI**



**Cougar B 02-68-1HN, B 02-69-1HN, B 02-67-1HN**

**Battery site**

**Active**

***Equipment Documented; Loc ID: 326875***

***Formerly served:***

***Baker B2-5, Fritzler B 02-19; Plugged & Abandoned | PA***



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources