

Inspection Photos
Location Name: A L Loft 1
Location ID: 317765



Photo 1 Location.



Photo 2 WH.

Inspection Photos
Location Name: A L Loft 1
Location ID: 317765



Photo 3 WH sign.

Photo 4 Prime mover.

Inspection Photos
Location Name: A L Loft 1
Location ID: 317765



Photo 5 Access Road to the Bridge.

Photo 6 Access road bridge has damage on both ends and center decking.

Inspection Photos
Location Name: A L Loft 1
Location ID: 317765



Photo 7 Access Road Bridge severe damage in the decking, irrigation water is visible below.

Photo 8 Access road bridge hole in decking Approx. 2.5 ft. x 1 ft.

Inspection Photos
Location Name: A L Loft 1
Location ID: 317765



Photo 9 Access road bridge has damage on both ends and decking.

Photo 10 Access road bridge has damage on both ends and decking.