

Inspection Photos

Loc: 324809

Operator: WESTERN OPERATING COMPANY

Inspection Date: 5/8/2024

County: KIOWA



Inspection Photos



May 8, 2024
+38.420562,-102.445059

Photo 1. Facing east at the access road toward the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 324809 | Date: 5/8/2024

Inspection Photos



Photo 2. Facing northeast towards the tank battery. The wind sock has been replaced.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 324809 | Date: 5/8/2024

Inspection Photos



Photo 3. There is an open hatch on the backside of the tank. This needs to be covered to prevent wildlife entry.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 324809 | Date: 5/8/2024

Inspection Photos



Photo 4. Facing southeast at the wellsite.



Inspection Photos



Photo 5. Facing east. There are two steel tanks that are unused that need to be removed along with various parts by the power pole.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 324809 | Date: 5/8/2024