

Inspection Photos

Loc: 324881

Operator: WESTERN OPERATING COMPANY

Inspection Date: 5/8/2024

County: KIOWA



Inspection Photos



Photo 1. Facing north toward the access road which is not establishing vegetation. It does not appear reclamation was completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 324881 | Date: 5/8/2024

Inspection Photos



Photo 2. Facing north toward the access road and location which is not establishing vegetation. It does not appear reclamation was completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 324881 | Date: 5/8/2024

Inspection Photos



Photo 3. Facing north at the abandoned location.



Inspection Photos



Photo 4. Facing south at the abandoned location.

