

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S96W/26NESW

Location ID: 335668

Date: 5/9/2024



Location Entrance – Photo #01072



Wellheads – Photo #01073

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S96W/26NESW

Location ID: 335668

Date: 5/9/2024



Gas Meters – Photo #01074



Gas Meters – Photo #01076

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S96W/26NESW

Location ID: 335668

Date: 5/9/2024



Gas Meters – Photo #01077



Tank Battery – Photo #01079

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S96W/26NESW

Location ID: 335668

Date: 5/9/2024



**Heater Tubing Debris – Photo #01080**