

Inspection Photos
Location Name: Weichel 27C-11HZ
Location ID: 331224



Photo 1: Overgrown vegetation



Photo 2: Overgrown vegetation

Inspection Photos
Location Name: Weichel 27C-11HZ
Location ID: 331224



Photo 3: Overgrown vegetation



Photo 4: Overgrown vegetation

Inspection Photos
Location Name: Weichel 27C-11HZ
Location ID: 331224



Photo 5: Overgrown vegetation, damaged fencing



Photo 6: Overgrown vegetation



Inspection Photos
Location Name: Weichel 27C-11HZ
Location ID: 331224



Photo 7: Overgrown vegetation



Photo 8: Overgrown vegetation

Inspection Photos
Location Name: Weichel 27C-11HZ
Location ID: 331224



Photo 9: Overgrown vegetation