

**Operator: HIGHPOINT OPERATING CORPORATION**  
**Location Name: Anschutz Equus Farms 4-62-20\_21 SWNW**  
**Loc ID: 444717**  
**Inspection: 713900517**



**Exhibit A**

**CA:** Missing wildlife netting on secondary containment. Comply with Rule 608.

**CA Resolution:** Operator has appropriately installed Wildlife Netting to comply with Rule 608.



**Exhibit A**

**CA:** Stained soil observed near unplugged hose that appeared to have soil moved over it. Remove stained soil per Rule 912.a.

**CA Resolution:** Operator has reported that the identified stained soil has been appropriately removed/disposed of to comply with Rule 912.a.