

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 44-16-694 Pit

Location ID: 421192



Photo # 6932 From entrance to location



Photo # 6933 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 44-16-694 Pit

Location ID: 421192



Photo # 6934 Location



Photo # 6935 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 44-16-694 Pit

Location ID: 421192



Photo # 6936 Location



Photo # 6937 Location

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC 44-16-694 Pit
Location ID: 421192



Photo # 6938 Location




Photo # 6939 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 44-16-694 Pit

Location ID: 421192



Photo # 6940 Location



Photo # 6941 Capacity on tank label faded & becoming illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 44-16-694 Pit

Location ID: 421192



Photo # 6942 Tank label contains inaccurate information

