

State of Colorado
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403787751

Date Received:

05/20/2024

Spill report taken by:

Spill/Release Point ID:

SPILL/RELEASE REPORT (INITIAL /w SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to ECMC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

OPERATOR INFORMATION

Name of Operator: SCOUT ENERGY MANAGEMENT LLC	Operator No: 10779	Phone Numbers
Address: 13800 MONTFORT DRIVE SUITE 100		Phone: (970) 501-5157
City: DALLAS State: TX Zip: 75240		Mobile: (970) 620-34546
Contact Person: Chris Patterson		Email: chris.patterson@scoutep.com

☐ Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 403787751

Initial Report Date: 05/13/2024	Date of Discovery: 05/11/2024	Spill Type: Recent Spill
---------------------------------	-------------------------------	--------------------------

Spill/Release Point Location:

QTRQTR SESE SEC 15 TWP 2N RNG 103W MERIDIAN 6

Latitude: 40.136319 Longitude: -108.937339

Municipality (if within municipal boundaries): County: RIO BLANCO

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

☒ Check this box if this spill/release is related to a loss of integrity of a flowline, pipeline, crude oil transfer line, or produced water transfer line.

Reference Location:

Facility Type: FLOWLINE SYSTEM ☐ Facility/Location ID No

Spill/Release Point Name: AC McLaughlin 64X Flowline ☐ Well API No. (Only if the reference facility is well) 05- -

☒ No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >0 and <1	Estimated Condensate Spill Volume(bbl): 0
Estimated Flow Back Fluid Spill Volume(bbl): 0	Estimated Produced Water Spill Volume(bbl): >=1 and <5
Estimated Other E&P Waste Spill Volume(bbl): 0	Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

Has the subject Spill/Release been controlled at the time of reporting? Yes

Land Use:

Current Land Use: NON-CROP LAND Other(Specify):

Weather Condition: Clear, Sunny 60 Degrees F

Surface Owner: FEDERAL Other(Specify): BLM

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On May 11, about 11:30 AM there was a flowline leak discovered on AC McLaughlin 64x after investigating a low flowline pressure alarm. Produced injection water and trace oil were release to ground. All fluids stayed on well pad location. Once it was discovered the operator immediately shut the well in and contained leak on location. All proper notifications were made, repair and clean up plans were made.

List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):

OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
	Entrada Inc.	Tim Dobransky	-	Emailed
	CPW	Garrett Smith	-	Emailed
5/11/2024	Rio Blanco County	Eddie Smercina	-	Emailed
5/11/2024	ECMC	Kris Neidel	970-846-5097	Left VM

REPORT CRITERIA

Rule 912.b.(1) Report to the Director (select all criteria that apply):

No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: _____ Public Water System: _____

Residence or Occupied Structure: _____ Livestock: _____

Wildlife: _____ Publicly-Maintained Road: _____

Yes Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery _____ (HH:MM)

Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 _____

Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? _____

Enter the Document Number of the Initial Accident Report, Form 22 _____

Was there damage during excavation? _____

Was CO 811 notified prior to excavation? _____

No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): _____

No	Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply: <input type="checkbox"/> The presence of free product or hydrocarbon sheen Surface Water <input type="checkbox"/> The presence of free product or hydrocarbon sheen on Groundwater <input type="checkbox"/> The presence of contaminated soil in contact with Groundwater <input type="checkbox"/> The presence of contaminated soil in contact with Surface water
No	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight's from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property. <input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 05/20/2024		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	4	4	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: Oil spilled and recovered was .23-system will not allow decimals.

Was spill/release completely contained within berms or secondary containment? YES Was an Emergency Pit constructed? NO

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) ☒ Soil ☐ Groundwater ☐ Surface Water ☐ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 20 Width of Impact (feet): 12

Depth of Impact (feet BGS): 5 Depth of Impact (inches BGS):

How was extent determined?

Field measured with tape/wheel

Soil/Geology Description:

High Clay

Depth to Groundwater (feet BGS) 3320 Number Water Wells within 1/2 mile radius: 0

If less than 1 mile, distance in feet to nearest

Water Well	None <input checked="" type="checkbox"/>	Surface Water	None <input checked="" type="checkbox"/>
Wetlands	None <input checked="" type="checkbox"/>	Springs	None <input checked="" type="checkbox"/>
Livestock	None <input checked="" type="checkbox"/>	Occupied Building	None <input checked="" type="checkbox"/>

Additional Spill Details Not Provided Above:

All Fluids stayed on well pad location. All distances above were obtained from the COGCC online GIS system. Depth of impact (line failure) was approximately 5 feet below grade. A below the pipe soil sample will be taken to show vertical delineation. Additional soil samples will also be taken along spill path and areas, all liquids were removed with a vac-truck.

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☐ Corrective Actions Completed (documentation attached, check all that apply)

☐ Horizontal and Vertical extents of impacts have been delineated.

☐ Documentation of compliance with Table 915-1 is attached.

☐ All E&P Waste has been properly treated or disposed.

☐ Work proceeding under an approved Form 27 (Rule 912.c).

Form 27 Remediation Project No: _____

☐ SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

OPERATOR COMMENTS:

On May 11, about 11:30 AM there was a flowline leak discovered on AC McLaughlin 64x after investigating a low flowline pressure alarm. Produced injection water and trace oil were release to ground. All fluids stayed on well pad location. Once it was discovered the operator immediately shut the well in and contained leak on location. All proper notifications were made, repair and clean up plans were made

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Chris Patterson

Title: Sr. HSE Coordinator Date: 05/20/2024 Email: chris.patterson@scoutep.com

COA Type	Description
----------	-------------

0 COA	
-------	--

ATTACHMENT LIST

Att Doc Num	Name
403796016	AERIAL IMAGE
403796017	PHOTO DOCUMENTATION

Total Attach: 2 Files

General Comments

User Group	Comment	Comment Date
Environmental	no BLM notice.	05/17/2024

Total: 1 comment(s)