

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC SAVAGE 9-26-6-94 W Pad

Location ID: 311595



Photo # 7530 From entrance to location



Photo # 7531 Location

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC SAVAGE 9-26-6-94 W Pad

Location ID: 311595



Photo # 7532 Location



Photo # 7533 Cellar lacks wildlife egress - Please refer to inspection 708903824 for corrective action