

Inspection Photos
Location Name: SEYLER/B10-64-1HN
Location ID: 331741



Photo #1
SEYLER/B10-64-1HN North pad
2: Wellsites
Wellsite(s), Battery entrance



Photo #2
DR B 10-12 (123-21225) Wellsite(s)
Plugged & Abandoned | PA
Cut / Capped
~ 10 yds.



Inspection Photos

Location Name: SEYLER/B10-64-1HN

Location ID: 331741



Photo #5

SEYLER B/15-69HN, SEYLER/B10-64-1HN S,N pads

Battery site

Active

Equipment Documented; Loc ID: 418894

Formerly served:

DR B 10-12, 2-10, Peterson B 10-25;

Plugged & Abandoned | PA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources