

Inspection Photos

Location Name: DR-65N64W/10SWSW

Location ID: 322962



Photo #1

DR 2-10 (123-12340) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 100 yds.



Photo #5

SEYLER B/15-69HN, SEYLER/B10-64-1HN S,N pads

Battery site

Active

Equipment Documented; Loc ID: 418894

Formerly served:

DR B 10-12, 2-10, Peterson B 10-25;

Plugged & Abandoned | PA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources