

This is a PLUGGED & ABANDONED WELL inspection.

Well(s): 1: Plugged & Abandoned | PA.

Battery: Active.

Centralized Battery serves 2 Location IDs

(418894, 331741).

(Well(s): 3: Producing | PR; 1: Shut-In | SI; 1: Temporarily Abandoned | TA).

[Location ID 331741 Formerly served: Well(s): 1: Plugged & Abandoned | PA.]

Centralized Battery Formerly served 2 Location IDs

(322962, 418882).

(Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID

(Pending).

Reference (Associated Well(s), Battery Inspections):

A.) Field Inspection Report doc. #707602806 and/or Location ID #418894 for PR Well(s) info.

B.) Field Inspection Report doc. #707602808 and/or Location ID #331741 for PR Well(s) info.

C.) Field Inspection Report doc. #707602810 and/or Location ID #418894 for SI Well(s) info.

D.) Field Inspection Report doc. #707602812 and/or Location ID #331741 for TA Well(s) info.

E.) Field Inspection Report doc. #707602814 and/or Location ID #331741 for PA Well(s) info.

F.) Field Inspection Report doc. #707602816 and/or Location ID #322962 for PA Well(s) info.

G.) Field Inspection Report doc. #707602818 and/or Location ID #418882 for PA Well(s) info.

H.) Field Inspection Report doc. #707602820 and/or Location ID #418894 for Battery / Facility, Equipment info.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume	corrective date
Plunger Lift	# 0		
Comment: Plugged & Abandoned PA. Equipment removed.			
Corrective Action:			Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 244545 Type: WELL API Number: 123-12340 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On FRI 05/17/2024 at approximately 14:34 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: DR-65N64W/10SWSW Location ID: 322962 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Inactive Shut-down.</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6-SRA on file. Plugging, cut/cap date: 10/09/2020. Approved. Plugged & Abandoned PA well GPS coordinates: 40.408350 / -104.543200</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	05/20/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602817	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6555310