

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RWF 34-26 Pad

Location ID: 335488



Photo # 7553 From entrance to location




Photo # 7554 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RWF 34-26 Pad

Location ID: 335488



Photo # 7555 Location



Photo # 7556 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RWF 34-26 Pad

Location ID: 335488



Photo # 7557 Location



Photo # 7558 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RWF 34-26 Pad

Location ID: 335488




Photo # 7559 Location



Photo # 7560 Staining around wellhead

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RWF 34-26 Pad

Location ID: 335488



Photo # 7561 Unmarked deadman



Photo # 7562 Same unmarked deadman from a different angle

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RWF 34-26 Pad

Location ID: 335488



Photo # 7563 Dead weeds/debris



Photo # 7564 Staining near wellhead