

Inspection Photos

05/06/2024

Operator: GUNNISON ENERGY LLC #10515

Location ID: 334446

Inspection Doc: 696205820

Gunnison County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 334446



Photo 1: Photos 1-2 taken from the south end of the working pad surface. Photos provide an overview of the Location from north, northeast, southeast to south. Photos also show interim reclamation to reduce the Location to areas only needed for production has not been performed in accordance with 1003 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 334446



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 334446



Photo 3: Photos taken from north end of the Location facing southeast and southwest. interim reclamation to reduce the Location to areas only needed for production has not been performed in accordance with 1003 Rules.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 334446



Photo 4: 2023 Google Earth aerial imagery. Photo provides an overview of the Location. Red polygon represent approximate ($\frac{3}{4}$ acres) areas of the current working pad surface not reasonably needed for production.

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 334446



Photo 5: Topsoil stockpile on the northwest end of the Location.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC #10515
Location ID: 334446



Photo 6: Well and tank battery facility.