


## Bradenhead Summary

<b>Well:</b>	Drake 18N
<b>API:</b>	123-51823

Bradenhead Test Data	Date	Event Measurement
Form 17 Bradenhead Test Report (psig)	2/24/2024	0
Abatement System Commission Date - MESSCO	5/17/2024	-



**Comments:** February 2024 initial rig release test had 0 PSI with no flow or pressure for entire test. However, monthly monitoring data has been above threshold. Based on monthly monitoring data, PDC has installed a MESSCO abatement system to remediate bradenhead pressure. A sample was collected 5/20/2024 and a new form 17 test has been requested following a 7 day abatement shut-in. PDC will continue to remediate pressure using the installed abatement system and reevaluate in 6 months.