



This facility  
uses  
non-emitting  
pneumatic  
controllers

TEP Rocky Mountain LLC

970-285-9377

GV 42-6 PAD

COC NONE	API
GV 42-6	05-045-06641
PA 332-6	05-045-13354
PA 432-6	05-045-13355
PA 532-6	05-045-13356
TW 11-6	05-045-06708

SWNE SEC 6/T7S/R95W  
GARFIELD COUNTY, CO  
EMS 911  
ACCESS FROM: HWY 6 & 24

Inspection Photos  
Location Name: GV 42-6  
Location ID: 334957  
Inspection Date: 5/20/2024

Location sign.

May 20, 2024 10:48:36 AM  
+39.4693N -108.0377W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: GV 42-6  
Location ID: 334957  
Inspection Date: 5/20/2024

300 bbl Condensate  
Steel AST.

May 20, 2024 10:48:43 AM  
+39.4693N -108.0377W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos  
Location Name: GV 42-6  
Location ID: 334957  
Inspection Date: 5/20/2024

200 bbl Produced Water  
Steel AST.

May 20, 2024 10:48:52 AM  
+39.4694N -108.0377W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos  
Location Name: GV 42-6  
Location ID: 334957  
Inspection Date: 5/20/2024

Erosion rills.

May 20, 2024 10:49:22 AM  
+39.4695N -108.0377W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos  
Location Name: GV 42-6  
Location ID: 334957  
Inspection Date: 5/20/2024

Erosion rills.

May 20, 2024 10:49:36 AM  
+39.4696N -108.0377W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos  
Location Name: GV 42-6  
Location ID: 334957  
Inspection Date: 5/20/2024

Erosion rills.

May 20, 2024 10:49:42 AM  
+39.4696N -108.0377W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: GV 42-6  
Location ID: 334957  
Inspection Date: 5/20/2024

Wellhead.

May 20, 2024 10:50:20 AM  
+39.4699N -108.0374W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources





Inspection Photos  
Location Name: GV 42-6  
Location ID: 334957  
Inspection Date: 5/20/2024

Wellheads.

May 20, 2024 10:50:37 AM  
+39.4699N -108.0376W



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources