

Operator: HIGHPOINT OPERATING CORPORATION
Location Name: Anschutz Equus Farms 4-62-33 NWNW
Loc ID: 437854
Inspection: 713900536



Exhibit A



Exhibit B



Exhibit C

CA: Electrical wires were observed daylighting on the production pad and black piping was stored in the interim area on the East side of the well location. Comply with Rule 606 to remove all debris.

CA Resolution: Operator has reported that the identified electrical wires and black piping observed during the inspection have been appropriately addressed to comply with Rule 606.