

# Inspection Photos

Loc: 322266

Operator: **JAVERNICK OIL**

Inspection Date: 5/20/2024

County: FREMONT



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east at the abandoned wellsite. The site has not been reclaimed and there are undesirable weeds and bare soil in this area of the wellsite.





## Inspection Photos



**Photo 2.** Facing southeast at the wellsite. There is bare soils and scattered debris remnants that remain.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:322266 | Date: 5/20/2024



## Inspection Photos



**Photo 3.** Facing southwest toward the surrounding undisturbed vegetation.

