

# Final Reclamation and Stormwater Inspection

Date: 05/21/2024

Operator: PDC ENERGY INC - 69175

Location ID: 317495

Inspection Document #: 708201266

Weld County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Hankins 22D  
Location ID: 317495



**Photo 1.** Facing north along the former access road; the access road appears to be progressing towards reclamation standards and regulations with uniform vegetation cover observed.

Inspection Photos  
Location Name: Hankins 22D  
Location ID: 317495



**Photo 2.** Facing south near the former well location. Vegetation cover does not appear to be reflective of the adjacent reference areas, possibly due to compaction or soil suitability issues.

Inspection Photos  
Location Name: Hankins 22D  
Location ID: 317495



**Photo 3.** Facing north near the former well location. Areas outside of the red line illustrate reference area vegetation cover and density, which does not appear reflective of the well location.