

# Final Reclamation and Stormwater Inspection

Date: 05/21/2024

Operator: PDC ENERGY INC - 69175

Location ID: 331006

Inspection Document #: 708201267

Weld County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Hankins 65N67W 22NESE  
Location ID: 331006



**Photo 1.** Taken near the southern portion of the former tank battery. Vegetation appears to be impacted either due to compaction, soil suitability issues, or both. Red polygon is approximate outline of former facilities. This location will remain in process until it can be inspected at a later date.



Inspection Photos  
Location Name: Hankins 65N67W 22NESE  
Location ID: 331006



**Photo 2.** Taken near the former tank battery. See comments in Photo 1.



Inspection Photos  
Location Name: Hankins 65N67W 22NESE  
Location ID: 331006



**Photo 3.** Taken near the former tank battery. See comments in Photo 1.



Inspection Photos  
Location Name: Hankins 65N67W 22NESE  
Location ID: 331006



**Photo 4.** Close up of reclaimed tank battery vegetation; key for scale.



Inspection Photos  
Location Name: Hankins 65N67W 22NESE  
Location ID: 331006



**Photo 5.** Close up of reference area vegetation taken east of the former tank battery location; key for scale.



Inspection Photos  
Location Name: Hankins 65N67W 22NESE  
Location ID: 331006



**Photo 6.** Apparent gas pipeline riser observed within the former tank battery location (north end). This location was inspected as the surface owner informed staff of the pipeline riser.