

Inspection Photos
Location Name: Gilbert 01-03
API Number: 125-10827



1. Well lease sign at well location.



2. View f wellhead.

Inspection Photos
Location Name: Gilbert 01-03
API Number: 125-10827



3. Tubing pressure at time of inspection.



4. Casing pressure at time of inspection.

Inspection Photos
Location Name: Gilbert 01-03
API Number: 125-10827



5. Well location overview.



6. Well location overview.