

# Inspection Photos

May 8th, 2024

Operator: Beeman Oil and Gas INC - 7125

Location ID: 306894

Inspection Document #: 714000758

La Plata County, CO

Township: NWNE 13 33N 13W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Grommett 2  
Location ID: 306894

5/8/24  
+37.109982,-108.207906  
116° SE



**Photo 1.** View of the project area taken from the northern edge facing center.  
Location sign remains on location.

Inspection Photos  
Location Name: Grommett 2  
Location ID: 306894



**Photo 2.** Cardinal photos taken from the center of the project area. Left photo facing north, right photo facing east.

Inspection Photos  
Location Name: Grommett 2  
Location ID: 306894



**Photo 3.** Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west. Vegetation within the project area appears consistent with the adjacent reference area.

Inspection Photos  
Location Name: Grommett 2  
Location ID: 306894



**Photo 4.** View of the access road taken from the project area facing south.

Inspection Photos  
Location Name: Grommett 2  
Location ID: 306894



**Photo 5.** View of straw wattles that remain on location.

Inspection Photos  
Location Name: Grommett 2  
Location ID: 306894



**Photo 6.** View of the vegetation transect within the project area facing northeast and the birds eye view of vegetation at midpoint of project area transect.

Inspection Photos  
Location Name: Grommett 2  
Location ID: 306894



**Photo 7.** Reference area comprised of sagebrush, juniper, smooth brome and grama sp.