

Inspection Photos

May 21st 2024

Operator: BP America Production Company -
10000

Location ID: 325529

Inspection Document #: 714000772

La Plata County, CO

Township: NESE 31 35N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Gearhart 1-31
Location ID: 325529



Photo 1. View of the project area taken from the southern edge facing center.

Inspection Photos
Location Name: Gearhart 1-31
Location ID: 325529



Photo 2. Cardinal photos taken from the center of the disturbance. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Gearhart 1-31
Location ID: 325529



Photo 3. Cardinal photos taken from the center of the disturbance. Left photo facing south, right photo facing west.

Inspection Photos
Location Name: Gearhart 1-31
Location ID: 325529



Photo 4. View of the area that was recently reseeded in the southwest corner of the disturbance. Area shows evidence of germinated species, including smooth brome. Location will be inspected at a future date to assess to vegetation establishment in this area.

Inspection Photos
Location Name: Gearhart 1-31
Location ID: 325529



Photo 5. View of the reference area comprised of pine, gambel oak and smooth brome.