

Inspection Photos
Location Name: Brown 2-6, 7, 21, 28-6
Location ID: 332306



Energy & Carbon Management Commission
40.17407, -104.69719, 1493.9m, 79°
May 21, 2024 13:33:04



Energy & Carbon Management Commission
40.17398, -104.69714, 1495.4m, 261°
May 21, 2024 13:33:35

Photo 1: Tank Battery Signs

Photo 2: Weeds/debris removed



Inspection Photos
Location Name: Brown 2-6, 7, 21, 28-6
Location ID: 332306



Photo 3: Debris



Photo 4: Debris

Inspection Photos
Location Name: Brown 2-6, 7, 21, 28-6
Location ID: 332306




Photo 5: Debris




Photo 6: Debris

Inspection Photos
Location Name: Brown 2-6, 7, 21, 28-6
Location ID: 332306




Photo 7: Debris




Photo 8: Debris

Inspection Photos
Location Name: Brown 2-6, 7, 21, 28-6
Location ID: 332306



Photo 9: Debris



Photo 10: Debris/weeds removed

Inspection Photos
Location Name: Brown 2-6, 7, 21, 28-6
Location ID: 332306



Photo 11: Debris/weeds removed



Photo 12: Debris/weeds removed