

Inspection Photos

May 21st 2024

Operator: Enduring Resources LLC - 10663

Location ID: 326339

Inspection Document #: 714000780

La Plata County, CO

Township: SWNW 9 34N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO


**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: West Animas University 9-2
Location ID: 326339



Photo 1. View of the well pad taken from the access point facing center.



API #: 067-07864

Inspection Photos
Location Name: West Animas University 9-2
Location ID: 326339



5/21/24
+37.220054,-107.864528
31° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the eastern interim reclamation area facing northeast. Vegetation comprised of western wheatgrass and rabbitbrush.

API #: 067-07864

Inspection Photos
Location Name: West Animas University 9-2
Location ID: 326339



Photo 3. Wildlife netting BMP on lube tank secondary containment is no longer functioning, maintenance is needed.

Inspection Photos
Location Name: West Animas University 9-2
Location ID: 326339



Photo 4. Reference area comprised of juniper, mountain mahogany, and sandberg bluegrass.

