

Inspection Photos

05/20/2024

Operator: GUNNISON ENERGY LLC - 10515

Location ID: 324464

Inspection Doc: 696205838

Gunnison County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324464



Photo 1: Photos taken from the northwest end of the Location, facing east and southeast. Photos provide an overview of the working pad surface.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324464



Photo 2: Photo shows areas on the north end of the Location where production equipment was previously located- areas have not been reclaimed pursuant to 1003.b requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324464



Photo 3: Photo taken from off-site areas northwest of the location where Operator had improperly stored equipment. Disturbed areas remain apparent.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324464



Photo 4: Photos 4-6 examples showing noxious weed establishment on the Location, and off-site adjacent areas where Operator disturbed during improper equipment storage.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324464



Photo 5: See comments under photo 4.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324464



Photo 6: See comments under photo 4.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324464



Photo 7: Photo 7-8 tank from the tank battery facility. Photos show holes drilled by Operator; fencing to restrict access by people or wildlife has not been installed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324464



Photo 8: See comments under photo 7.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources