

# Inspection Photos

Loc: 483886

Operator: BNL (ENTERPRISE) INC

Inspection Date: 5/21/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



May 21, 2024  
+37.545594,-104.127792

**Photo 1.** Facing north along the access road. The road has been regraded and crowned.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:483886 | Date: 5/21/2024



## Inspection Photos



**Photo 2.** Facing north along the road. The vehicle ruts outside of the road have been raked out.





## Inspection Photos



**Photo 3.** Facing northwest toward the access road. The side of the road needs to be seeded and stabilized.





## Inspection Photos



**Photo 4.** Facing northwest toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:483886 | Date: 5/21/2024



## Inspection Photos



**Photo 5.** Facing west at the topsoil pile. It does no appear that seeding has been performed.





## Inspection Photos



**Photo 6.** Facing toward the soil stock pile. There weeds beginning to grow along the soil pile. The topsoil must be seeded to prevent weed establishment.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:483886 | Date: 5/21/2024



## Inspection Photos



**Photo 7.** There are several areas where the silt fence is not maintained.





## Inspection Photos



**Photo 8.** Facing toward the wellhead.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:483886 | Date: 5/21/2024