



00060416

WELL SITE INSPECTION FORM

Well Name DAONA INV. #2 API Number 05 - -
Operator AMOCO Permit # _____
Location NW 2-1N-68W County WELD
Field SPINDLE? Inspector _____
AL/PA/DA Inspection Results: Well Status:
Pass(Y) _____ Fail(N) _____ Date _____ FN _____ FD _____ WO _____ PR _____ SI ☒

=====

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
Consistent with APD casing Program? YES _____ NO _____ Returns _____
Rig _____ BOP'S _____ Contact _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
Drilling Pits: Closed _____ Open _____ Wellhead Installed: _____ Sign: Yes ☒ No _____
Tank ID: Yes _____ No _____ N/A _____ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
Equipment _____ Meter Run: Yes _____ No _____
Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: _____ Date Permit Expired: _____
Hole Plugged: Yes _____ No _____ Pits Backfilled: Yes _____ No _____
Material Buried: Yes _____ No _____ N/A _____ Site Clean: Yes _____ No _____
Bond Release OK: Yes _____ No _____ Fed _____ Hole Marker: Yes _____ No _____

Date of Safety/Status Inspection 5-23-90

Comments: RODS IN HOLE, HEAD LAYING TO THE SIDE. TO BE
P&A?

Violations: Yes _____ No ☒ Notice Sent: Yes _____ No _____ Date Sent: _____