

Inspection Photos

API: 071-09500

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 5/24/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast along the access road. There is vehicle rutting along the road that will need to be repaired.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 2. Facing southwest toward the wellsite.



Inspection Photos



Photo 3. Facing toward the pw pit.

