

Inspection Photos

API: 071-06516

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 5/24/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the main access road. The two cattle guards have been removed.



Inspection Photos




Photo 2. There is a pile of gravel where the cattle guards were removed.



Inspection Photos



Photo 3. Facing northwest toward the wellsite.



Inspection Photos



Photo 4. Facing west toward the fill slope which is stabilized with vegetation.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06516 | Date: 5/24/2024