

Inspection Photos

API: 071-07929

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 5/24/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the access road. There is vehicle rutting along the road which may need more gravel for stabilization.



Inspection Photos



Photo 2. Facing southwest along the access road. There is vehicle rutting along the road which may need more gravel for stabilization.



Inspection Photos



Photo 3. Facing southwest toward the wellsite.

