

Inspection Photos  
Location Name: Timbro LD06-64HN  
Location ID: 433177




Photo 1 – Wellhead



Photo 2 – Wellhead Sign

**Inspection Photos**  
**Location Name: Timbro LD06-64HN**  
**Location ID: 433177**



**Photo 3 – Wellhead**



**Photo 4 – Overview**



**Inspection Photos**  
**Location Name: Timbro LD06-64HN**  
**Location ID: 433177**



**Photo 5 – VRU and Compressor**



**Photo 6 – ECDs and VRU**

**Inspection Photos**  
**Location Name: Timbro LD06-64HN**  
**Location ID: 433177**




**Photo 7 – Gas Meters**



**Photo 8 – Separator**



**Inspection Photos**  
**Location Name: Timbro LD06-64HN**  
**Location ID: 433177**



**Photo 9 – Nitrogen Tank**



**Photo 10 – VRT**

Inspection Photos  
Location Name: Timbro LD06-64HN  
Location ID: 433177



Photo 11 – Tank Battery



Photo 12 – Tank Battery Sign