

Inspection Photos
Location Name: Timbro LD12-78HN
Location ID: 421859



Photo 1 – Heater Treater



Photo 2 – Tank Battery

Inspection Photos
Location Name: Timbro LD12-78HN
Location ID: 421859



Energy and Carbon Management Commission
40.77218, -103.93397, 4859.3ft
05/21/2024 11:17:56

Photo 3 – Tank Battery Sign



Energy and Carbon Management Commission
40.77147, -103.93423, 4853.0ft
05/21/2024 11:18:17

Photo 4 – Pumping Unit – Unused Tubing

Inspection Photos
Location Name: Timbro LD12-78HN
Location ID: 421859




Photo 5 – Unused Rods

Photo 6 – Wellhead

Inspection Photos
Location Name: Timbro LD12-78HN
Location ID: 421859



Photo 7 – Tank Battery – Backside of Tanks



Photo 8 – ECD and Nitrogen Tank