

Inspection Photos
Location Name: Keota PC LB26-62HN
Location ID: 431312




Photo 1 – Wellhead – Stained Soil



Photo 2 – Stained Soil

Inspection Photos
Location Name: Keota PC LB26-62HN
Location ID: 431312



Photo 3 – Wellhead Sign



Photo 4 – Stained Soil

Inspection Photos
Location Name: Keota PC LB26-62HN
Location ID: 431312



Photo 5 – Unused Wellhead Parts



Photo 6 – Separators

Inspection Photos
Location Name: Keota PC LB26-62HN
Location ID: 431312



Photo 7 – Gas Meters



Photo 8 – VRU

Inspection Photos
Location Name: Keota PC LB26-62HN
Location ID: 431312



Photo 9 – Nitrogen Tank



Photo 10 – Tank Battery

Inspection Photos
Location Name: Keota PC LB26-62HN
Location ID: 431312



Energy and Carbon Management Commission
40.71845, -104.06897, 4884.5ft
05/21/2024 12:06:28

Photo 11 – Tank Battery Sign