

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 232-28 Pad

Location ID: 324163



Photo # 7888 From entrance to location




Photo # 7889 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 232-28 Pad

Location ID: 324163

May 22, 2024 at 12:16:13 PM  
CO



Photo # 7890 Location

