

Inspection Photos

May 24th, 2024

Operator: BP America Production Company -
10000

Location ID: 385638

Inspection Document #: 714000788

La Plata County, CO

Township: NESE 27 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

5/24/24
+37.273844,-107.726695
186° S



Photo 1. View of the project area taken from the northern edge facing south. Note: access road remains/runs through project area to access residential home to the south.



Photo 2. View of the western portion of the project area. Note: horses have been introduced and fenced into the area, grazing appears to be affecting establishment of perennial vegetation in the western portion of the project area.

Inspection Photos
Location Name: Lobato 1-27
Location ID: 385638



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of the eastern portion of the project area. Note: Area has not been grazed and appears to be progressing towards 1004 reclamation standards.

API #: 067-06534

Inspection Photos

Location Name: Lobato 1-27

Location ID: 385638



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area comprised of pine, gambel oak and smooth brome.

API #: 067-06534