

Inspection Photos

May 24th, 2024

Operator: BP America Production Company -
10000

Location ID: 325941

Inspection Document #: 714000790

La Plata County, CO

Township: NESE 18 35N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Litton Federal 1
Location ID: 325941

5/24/24
+37.299905,-107.673199
76° E



Photo 1. View of the well disturbance taken western edge facing east.

Inspection Photos
Location Name: Litton Federal 1
Location ID: 325941



Photo 2. Musk thistle and mullein observed on location.

Inspection Photos
Location Name: Litton Federal 1
Location ID: 325941



Photo 3. View of gully erosion forming on the eastern edge of the disturbance.