

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Story Gulch Unit/8506D-25 F25496

Location ID: 415182

Date: 5/22/2024



Location Entrance – Photo #01291



Wellheads – Photo #01298

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Story Gulch Unit/8506D-25 F25496

Location ID: 415182

Date: 5/22/2024



Gas Meters – Photo #01294



Gas Meters – Photo #01301

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Story Gulch Unit/8506D-25 F25496

Location ID: 415182

Date: 5/22/2024



Gas Meters – Photo #01292



Gas Meters – Photo #01293

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Story Gulch Unit/8506D-25 F25496

Location ID: 415182

Date: 5/22/2024



**Tank Battery/No Signage – Photo #01296**



**Tank Battery/No Signage – Photo #01299**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Story Gulch Unit/8506D-25 F25496

Location ID: 415182

Date: 5/22/2024



Stored Supplies – Photo #01303



Stored Supplies/Equipment – Photo #01304