

Final Reclamation Inspection

May 22, 2024

Operator: SHELL OIL COMPANY #78100

Location ID: 387762

Inspection Document #: 697505304

Logan County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: L C HOXIE 1
Location ID: 387762



Photo 1. Photo taken from the well location, facing North. Photo illustrates the well location is reflective of reference crop areas.



Inspection Photos
Location Name: L C HOXIE 1
Location ID: 387762



Photo 2. Reference photo taken southwest of location, facing Northwest. See comments under Photo 1.