

## Inspection Photos

Location Name: GLOVER USX B-65N64W/15NWSE

Location #: 410190



**Photo #1**

**Glover USX B 15-02CD (123-30260) Wellsite**

**Plugged & Abandoned | PA**

*Cut / Capped*

*~ 25 yds.*



**Photo #2**

**Glover USX B 15-02CD, Loustalet B15-10, B 15-09,**

**B 15-15X, B15-16, B 15-23 Battery site**

**Abandoned: MOST Equipment Removed**

**Plugged & Abandoned | PA (6: wells).**



**COLORADO**


**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: GLOVER USX B-65N64W/15NWSE

Location #: 410190



### Photo #3

Glover USX B 15-02CD, Loustalet B15-10, B 15-09,  
B 15-15X, B15-16, B 15-23 Battery site

**Abandoned: MOST Equipment Removed**

**Unnecessary Equipment:** Gas meter run pig launcher,  
2-dump line(s), 3-sign(s), temporary fencing.

*West side of former Battery site*



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources