

Inspection Photos

Location Name: LOUSTALET B-65N64W/15SWSE

Location #: 302196



Photo #1

Loustalet B 15-15X (123-27338) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 15 yds.



Photo #2

Glover USX B 15-02CD, Loustalet B15-10, B 15-09,

B 15-15X, B15-16, B 15-23 Battery site

Abandoned: MOST Equipment Removed

Plugged & Abandoned | PA (6: wells).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources