

Inspection Photos

Location Name: CAERUS PICEANCE LLC, SG/D36 496

Location ID: 424630

Date: 5/22/2024



May 22, 2024 at 13:52:28
Parachute CO 81635
United States

Location Entrance – Photo #01306



May 22, 2024 at 13:55:33
Parachute CO 81635
United States

Wellheads – Photo #01314

Inspection Photos

Location Name: CAERUS PICEANCE LLC, SG/D36 496

Location ID: 424630

Date: 5/22/2024



Gas Meters – Photo #01308



Gas Meters – Photo #01311

Inspection Photos

Location Name: CAERUS PICEANCE LLC, SG/D36 496

Location ID: 424630

Date: 5/22/2024



Gas Meters – Photo #01312



Gas Meters – Photo #01313

Inspection Photos

Location Name: CAERUS PICEANCE LLC, SG/D36 496

Location ID: 424630

Date: 5/22/2024



Tank Battery/No Signage – Photo #01310



Stored Supplies/Equipment – Photo #01309