

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEVER A16

Location ID: 311676

API # 045-15232



**Photo # 8443 From entrance to location**



**Photo # 8444 Location**

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEVER A16

Location ID: 311676

API # 045-15232



Photo # 8445 Location

Photo # 8446 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEVER A16

Location ID: 311676

API # 045-15232



**Photo # 8447 Possible wellhead leak/gas bubbling up around wellhead through water in cellar**



**Photo # 8448 Possible wellhead leak/gas bubbling up around wellhead through water in cellar**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DEVER A16

Location ID: 311676

API # 045-15232



**Photo # 8449 Possible wellhead leak/gas bubbling up around wellhead through water in cellar**