

Inspection Photos

API: 071-08229

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 5/28/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast along the access road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. Facing south along the access road. A new culvert was installed with outlet protection.



Inspection Photos



May 28, 2024
+37.061314,-104.614159

Photo 3. Facing west toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-08229 | Date: 5/28/2024