

Inspection Photos

API: 071-09262

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 5/28/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south along the access road. A new culvert was installed with outlet protection.



Inspection Photos



Photo 2. Facing southwest toward the location.

