

# Inspection Photos

API: 071-07615

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 5/28/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing south along the access road. There is vehicle rutting along the road that needs to be repaired.





## Inspection Photos



**Photo 2.** Facing south along the access road. This culvert is damaged and the outlet has filled in with sediment.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 3.** Facing north toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources