

Inspection Photos

API: 071-07764

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 5/28/2024

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing northeast toward the wellsie.



Inspection Photos



Photo 2. The perennial vegetation is established along the fill slope.



Inspection Photos



Photo 3. There is rip/rap outlet protection along the south side of the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-07764 | Date: 5/28/2024